Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number
EDR ID Number

ED663 REGULATOR NY Spills S110138666
North AVE V WEST 11THST N/A

1/2-1 BROOKLYN, NY

0.962 mi.

5077 ft. Site 8 of 8 in cluster ED

 Relative:
 SPILLS:

 Higher
 Name:
 REGULATOR

 Actual:
 Address:
 AVE V WEST 11THST

 13 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0909839 / 2009-12-07

0909839 Facility ID: Facility Type: ER DER Facility ID: 371504 Site ID: 422570 DEC Region: 2 Spill Cause: Other Spill Class: C4 2401 SWIS: Spill Date: 2009-12-04 Investigator: **SFRAHMAN** Referred To: Not reported Reported to Dept: 2009-12-05 CID: Not reported

Water Affected: CONEY ISLAND CREEK Spill Source: Commercial/Industrial

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2009-12-05
Spill Record Last Update: 2009-12-07
Spiller Name: Not reported
Spiller Company: CONTARCTOR
Spiller Address: Not reported
Spiller Company: 999

Contact Name: GREG REARDON

DEC Memo: "12/07/09 Referred to Water Division.(sr)"

Remarks: "pump stion under construction, insufficient pumps relase into coney

island creek, spill is still ongoing."

All Materials:

422570 Site ID: Operable Unit ID: 1178405 Operable Unit: 01 Material ID: 2171778 Material Code: 0062A Material Name: raw sewage Case No .: Not reported Material FA: Other

Quantity: Not reported Units: Not reported Recovered: Not reported Oxygenate: Not reported